

What happens when part of the shroud assembly breaks?



Note the top 6' of the mast...



How did this happen?

So the shackle broke though. Here is the other side. Note the fatigue.



Long story short I was in 1-5 mph wind and a wake it me and just put it over the edge. Caps were at 12 on a Loos gage. I'll be using Aluminum backing plated now.